

CLASSIFIED MESSAGE

ORIG :
 UNIT :
 EXT :
 DATE : 7 DEC 70

S E C R E T

ROUTING

1		4	
2		5	
3		6	

10 DEC 70 23 44

TO :
 FROM :
 CONF :
 INFO :

	DEFERRED	PRIORITY	INITIALS
X	ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

PAGE 1 OF 2

TO

INFO

CITE

9974

SUBJ: EVAL OF ☐ MISSION C-150-C, 6 OCT 70

1. IMAGE QUALITY: IMAGE QUALITY AND INTERPRETATION SUITABILITY
 ARE FAIR TO GOOD. CLOUD COVER OBSCURES APPROX 50 PCT OF ENTIRE MSN.

2. MSN DATA:

- A. MSN NO: C-150C
- B. DATE: 6 OCT 70
- C. CAM NO: 231 (B CAM); A/C TYPE: U2R
- D. CAM MODE: 3
- E. T/O: 0110Z; C/ON: (MODE 3) 0325Z
- F. FILM TYPE: 3400
- G. SHUTTER SPEED: N.a.
- ✓ H. FILTER: W-12
- I. PROC SITE: CARD

3. ORIG NEG:

- A. EXPOSURE: GOOD.
- B. DENSITY AND CONTRAST: GOOD.

COORDINATING OFFICERS

S E C R E T

RELEASING OFFICER

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

Signal Center Transmission Copy - DO NOT DETACH - Forward with Master

25X1

25X1

25X1

CLASSIFIED MESSAGE

S E C R E T

ORIG :
UNIT :
EXT :
DATE :

TO :

FROM:

CONF:

INFO :

PAGE 2 OF 2

ROUTING			
1		4	
2		5	
3		6	

RESPONSES	DEFERRED	PRIORITY	INITIALS
	ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

TO

INFO

CITE

C. PHYSICAL DEGRADATIONS: NONE OTHER THAN A FEW MINOR

PINHOLES.

D. IMAGED DEGRADATIONS: THE 9R MATERIAL EXHIBITS PLUS DENSITY LINES RUNNING THE LENGTH OF FILM, 1.4 AND 4.2 INCHES FROM INBOARD EDGE. OUTBOARD AND INBOARD EDGE STATIC IS PRESENT INTERMITTENTLY THROUGHOUT THE MSN ON THE 9L AND 9R MATERIAL.

E. AUXILIARY DATA: THE FR COUNTER FAILED TO OPERATE EXCEPT DURING THE POST-FLIGHT PORTION OF MSN. THE POSITION INDICATOR FAILED TO OPERATE PROPERLY.

F. OTHER: MODE OF PHOTOGRAPHY FOR FIRST 59 FRS IS UNKNOWN. THERE-AFTER MODE 3 WAS USED.

4. POSITIVES: FAIR TO GOOD FOR INTERPRETATION.

END OF MESSAGE

COORDINATING OFFICERS

S E C R E T

Y OTHER THAN THE ISSUING OFFICE

sion Copy - DO NOT DETACH - Forward with Master

25X1
25X1